



Digital Test Thermometer


with Stainless Steel Probe

Operating Instructions

- Press ON/OFF - thermometer is ready for use.
- Press °C / °F Button to change from °C to °F
- Range: -50°C to +150°C & °F

Caution

- Always keep the thermometer head away from direct heat or cold
- The probe is very sensitive:
do not use an abrasive to clean it.
- Do not use in a microwave or conventional oven.



Changing the Battery

Brannan Thermometers

Cleator Moor Cumbria

England

www.brannan.co.uk