



Digital Test Thermometer

with Stainless Steel Probe

Specifications

• Range: -50 to +150°C / -58 to +302°F

Accuracy: +/-1°C / 2°F
Resolution: 0.1°C
Sampling: 1 second

Battery: 1.5V - 1 x LR44 (included)
Automatic power off after 45 minutes


Operating Instructions

- Press ON/OFF button to turn on (the thermometer will perform a self test then jump to normal display).
- Press °C/°F button once to change temperature unit.
- Insert probe into test substance 25mm (1")
- Press HOLD button to retain reading
- · Press ON/OFF button again to turn off

Caution

- Always keep the thermometer head away from direct heat or cold
- The probe is very sensitive: do not clean with an abrasive
- · Do not use in a microwave or conventional oven.

Changing the Battery





Brannan Thermometers Cleator Moor Cumbria England www.brannan.co.uk